

Scanner Configuration Sheet (1000A)

1000A



Title: 1500

Created Date: Fri Aug 23 2019 11:53:45 GMT+0200 (közép-európai nyári idő)

Note:

h



Enter Setup



Restore Default Setting

Scanner

Status Indicator

2



Good Read Beeper Len. :Shortest

3



LED Duration :4 x10ms

Beeper Volume :

h



0x04

5



Validate

Interface

General Setting

6



Keyboard Wedge : PCAT (Hungarian)

7



0x03

8



0x01

9



Validate

10



Laptop Support :Enable

Keyboard/HID Settings

11



Digits Transmission :Numeric Keypad

Symbology

Code 128/Codabar Symbology

Code 128



Security Level:High

Codabar



Security Level:High

UPC/EAN Symbology

EAN13



Security Level:High

GS1 Databar Symbology



Security Level:High

Code 11/Code 93/MSI/Plessey/Telepen Symbology

Code 11



Transmit Check Digit:Disable

Code 39 Symbology



Security Level:High

Output Format

Char Substitution



Code 11:Disable



Trioptic Code 39:Disable

12



Update